

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,873,550 B2
DATED : March 29, 2005
INVENTOR(S) : Mihnea

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5.


Line 58, "0 to 12V." should read -- 0 to -12V --.

Column 6.

Line 15, "0 to 12V." should read -- 0 to -12V --.

Signed and Sealed this

Tenth Day of January, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office